



Introduction & Project Goals

In 2020 the City of Portsmouth renovated the former Lt. Paul A. Double U.S. Army Reserve Center into a public senior activity center. The building was originally constructed in 1957. Due to budgetary constraints, the assembly hall was not included in the structural modifications, however, it was updated with new windows, HVAC, and lighting. The purpose of this project is to bring the assembly hall up to current structural code for use as an emergency shelter. This will include a structural assessment, structural analysis, and research of structural improvement options.





Figure 1: Locus Map



Figure 2: Senior Activity Center






Portsmouth Senior Center Structural Assessment Sage Cawthern (PM), Emily Clickner, Joseph Jorgens, Ryan Savoy & Guillermo Sepulveda Project Sponsor: Wunderlich-Malec Engineering Faculty Advisor: Dr. Robert Henry

Department of Civil and Environmental Engineering, University of New Hampshire, Durham, NH 03824

Structural Assessment



- An evaluation of the existing exterior and interior structural conditions revealed the following:
- Long window spans in the East and West walls, as well as new wall penetrations in the West wall, caused insufficient lateral capacity within the shear walls.
- lighting fixtures and HVAC. The observation of interior and exterior wall step cracking during the site visit could be a
- result of large in-plane loads. The bubbled interior wall surface along the East wall indicated the presence of moisture
- within the wall.
- with an ASCE 7-10 risk category IV distinction.
- An analysis of the pilasters found them to have insufficient moment capacity.



Figure 7: Exterior Wall

Step Cracking



Figure 8: Exterior Step Cracking by Window Along East Wall

Figure 9: Windows & New Wall Penetrations in West Wall



Figure 11: Interior Wall Step Cracking



Figure 12: New Paint Bubbling From Interior Moisture



Figure 13: Joists Resting on Masonry Wall

Structural Analysis

- To analyze the structural members of the assembly hall the following loads were considered: Dead Load Roof Live Load
 - Self Weight of Framing Members
 - Weight of the Roof
 - Ductwork and Lighting

The analysis was performed using Visual Analysis[©] software. The components analyzed include the pilasters, shear walls, and girders.

References

American Society of Civil Engineers. (2010). Minimum Design Loads for Buildings and Other Structures. ASCE 7-10. Reston, Virginia. Community Development. (n.d.) *New Senior Activity Center.* City of Portsmouth,

http://cityofportsmouth.com/community/new-senior-activity-center. The Masonry Society. *Building Code Requirements for Masonry Structures.* TMS 402. International Code Council. (October 2015). 2015 International Building Code. IBC 2015.

The roof framing was found to be adequate despite new loads introduced from updated

The lack of connection between the joists and walls is a violation of current code guidelines. The lack of reinforcing of the masonry walls does not meet the requirements for a building

Figure 10: Windows Along East Wall

Figure 14: New Lighting and HVAC

- Flat Roof Snow Load
- Equivalent Lateral Seismic Force
- Wind Load

Issue to be Add Unreinforced masonry walls

Roof framing no anchored to stru Pilasters – Insufficient mor capacity

West wall-Insufficient in s

Renovation O Anchoring and t elements togeth (Roof angle clips

Out of plane wal bracing with tim steel members

In plane wall strengthening -Shotcrete

In plane wall strengthening -Fiberglass-reinfo plastic (FRP)

Special thanks to our project faculty advisor, Dr. Robert Henry, capstone coordinator, Anthony Puntin, and project sponsors, Tim Nichols, Tyler Renz, and Carter Terry for their support and guidance throughout this project.



Wunderlich-Malec

Structural Improvements

ressed	Renovatio	n Options
ot ucture ment	 FRP overlay applied Reinforced shotcreted the interior side of the interior side of the walls Timber strong back the interior side of the walls Use ledger angles to joists to the walls Timber strong back the interior side of the walls Timber strong back the interior side of the walls Finder strong back the interior side of the walls FRP overlay applied Reinforced shotcreted 	e system installed on he walls n on the interior side system installed on he walls connect the roof system installed on he wall n installed on the valls to walls
mear	the interior side of the walls	
ption	Pros	Cons
tying ner s)	 Helps resist out-of- plane loading (wind and seismic loads) Stronger composite diaphragm system Relatively inexpensive 	 Accessibility to the roof and installation of clip angles can be hard due to limited working room
ll nber or	 Stiffens the walls to increase flexural, bending, and shear capacity in the walls Reduces the tension forces in the walls, which will help to reduce further step cracking Reduces the tension 	 Wall thickness increases resulting in less area inside of the assembly hall Costly if new foundations are needed to support new timber/steel members Adds significant weight to the building which leads to greater seismic forces FRP materials and
Forced	forces in the walls, which will help to reduce further step cracking	 installation can be expensive Requires unique skilled labor

Acknowledgements