

# Lee Center Intersection Road Safety Audit

Jesse Jakubajtys (PM), Christian Milioto, Calvin Poitras




Department of Civil and Environmental Engineering, University of New Hampshire, Durham, NH 03824

### Introduction

The intersection in the town center of Lee, NH features unique triangular geometry that has raised concerns among stakeholders. The project team was tasked with performing a Road Safety Audit (RSA) on the intersection. The team dedicated the Fall semester to identifying main safety concerns with the intersection and dedicated the Spring semester to designing alternatives.

### Location



Locus map of intersection.

- Intersection is located just a few minutes away from the Lee traffic circle and the University of New Hampshire's main campus.
- NH 155 is the primary road through the intersection, running North to South from Durham to Lee.

### Safety Improvements

There are some proposed improvements that are consistent with each design including:

- Streetlights
- Directional signs



#### On Site Observations

#### Main concerns observed on site:

- Junctions with acute geometry
- Poor sight lines



Junction of NH 155 and George Bennett Rd. shows poor sight lines.

- Insufficient signage
- Lack of pedestrian accommodations
- High speeds on NH 155
- Evening sun glare




Photo highlights lack of pedestrian features at intersection.

## **Proposed Alternatives**

Photo shows

poor signage.

#### **Existing Intersection**




Existing intersection with no adjustments. Does not include any proposed alternatives or address any concerns.

### Proposed "T" Junctions




Proposed intersection with re-worked junctions. Design addresses poor sight lines and high speeds on NH 155.

#### Proposed Pedestrian Features



Existing intersection featuring sidewalks, crosswalks, and bike lanes. Design addresses pedestrian concerns, not geometry.

### Proposed Roundabout




Proposed roundabout retrofit with pedestrian accommodations. Same roundabout design also created without pedestrian features. Design addresses most concerns.


### Public Input

#### Additional concerns noted by stakeholders:

- Dangerous crossing traffic
- Lack of streetlights
- Historic aesthetic of area



Survey results of stakeholder's concerns



Modes of transportation used by respondents

The survey results confirmed the thought that the intersection is unsafe and constitutes a Road Safety Audit.

#### Conclusions

- Develop a range of alternatives that address some or all safety concerns within the intersection
- Present findings in a design portfolio with cost estimates and benefits/challenges list
- Provide Lee with potential options to pursue in the future

## Acknowledgements

- Dr. Kyle Kwiatkowski (Faculty Advisor)
- Bill Lambert (Project Sponsor)
- Michael Dugas (Project Sponsor)
- Michelle Marshall (Project Sponsor)
- Lee, NH Select Board

### References

- FHWA Road Safety Audit Guidelines
- AASHTO (2011)
- Road Safety Audit Bow, NH
- Roundabouts: An Informational Guide